

EXECUTIVE SUMMARY	i
INTRODUCTION	3
1.1 PHYSICAL SETTING	3
1.2 SABINE RIVER AUTHORITY OF TEXAS	8
1.3 EXPLORER PIPELINE COMPANY	9
1.4 PROPERTIES OF MTBE AND OTHER GASOLINE COMPONENTS	11
2. EVENT CHRONOLOGY	14
3. SPILL EVENT AND INITIAL RESPONSE	22
3.1 DESCRIPTION OF SPILL	22
3.2 SPILL SITE AND EAST CADDO CREEK ACTIVITIES	23
3.3 LAKE TAWAKONI	23
3.4 DOWNSTREAM OF LAKE TAWAKONI	24
4. MONITORING ACTIVITIES	25
4.1 WATER	25
4.2 RESERVOIR FISHES	38
4.3 RESERVOIR SEDIMENTS	38
4.4 CREEK SEDIMENTS	39
4.5 SPILL SITE	40
4.6 GROUNDWATER	42
5. TREATMENT AND REMEDIATION	43
5.1 WATER	43
5.2 SPILL SITE AND CREEK	45
6. AGENCY INVOLVEMENT	48
6.1 DEPARTMENT OF TRANSPORTATION OFFICE OF PIPELINE SAFETY	48
6.2 NATIONAL TRANSPORTATION AND SAFETY BOARD	48
6.3 ENVIRONMENTAL PROTECTION AGENCY	49
6.4 TEXAS NATURAL RESOURCE CONSERVATION COMMISSION	49
6.5 TEXAS PARKS AND WILDLIFE DEPARTMENT	50
6.6 TEXAS DEPARTMENT OF HEALTH	51
7. WATER SUPPLIERS AND USERS	52
7.1 CITY OF DALLAS	52
7.2 WATER CUSTOMERS WITH CONTAMINATED INTAKES	52
7.3 WATER CUSTOMERS WITH UNCONTAMINATED INTAKES	54
8. PUBLIC INVOLVEMENT	56
9. CONTINUING ISSUES	57
10. REFERENCES	58

FIGURES

*Sabine River Authority of Texas Summary Report
MtBE Contamination in Lake Tawakoni from Gasoline Pipeline Rupture*

Figure ES.i	Lake Tawakoni Area Map.....	vi
Figure 1.1	Lake Tawakoni and Watershed Area.....	4
Figure 1.2	Geologic Map of East Caddo Creek.....	6
Figure 1.3	Raw Water Intakes in Lake Tawakoni	10
Figure 2.1	MtBE Contamination Near West Tawakoni Raw Water Intake.....	17
Figure 2.2	East Caddo Creek Surface Water Contamination.....	17
Figure 4.1	MtBE Mass Inflow into Lake Tawakoni.....	26
Figure 4.2	Lake Tawakoni and East Caddo Creek Monitoring Locations.....	28
Figure 4.3	Lake Tawakoni Monitoring Locations March 11-14, 2000.....	30
Figure 4.4	Surface Sediment Contamination in East Caddo Creek.....	41