



UPDATE

Lake Fork Reservoir – Soil Cement Repairs
SABINE RIVER AUTHORITY OF TEXAS
LAKE FORK
353 PR 5183, QUITMAN, TX 75783

February 7, 2022

The water level at Lake Fork Reservoir was lowered to an elevation of approximately 397-ft to make repairs and further assess the Lake Fork Dam. Underwater inspections were conducted which identified additional areas that are also in need of repair.

At this time, the SRA plans to hold the reservoir at an elevation of 397-ft while these additional repairs are performed. SRA plans to increase manpower with staff from other divisions to assist with expediting the repairs.

Lake side property owners should continue to inspect and make necessary repairs to boathouses, piers, retaining walls and related structures. Construction approval applications for this type of activity may be obtained from the Lake Fork Division Office (903-878-2262).

For more information contact the Lake Fork Division Office (903-878-2262).